



GNART

Goniómetro en acero inoxidable para medir el grado en articulaciones.
Guías laterales no incluidas.

Stainless steel goniometer to measure the joint angles of the body. Lateral guides are not included.


Goniomètre en acier inoxydable pour mesurer l'angle des articulations. Guides latéraux non comprises.

Características generales	
Normativas y seguridad	PRODUCTO CE Fabricado en España


General features	
Rules and security	CE marking product. Made in Spain

Caracteristiques generales	
Normes et securité	Produit CE. Fabriqué en Espagne

Accesorios



GUILAT3
Guías laterales 60cm




GUILAT2
Guías laterales 110cm




GUILAT1
Guías laterales 126cm

Accessories



GUILAT3
Lateral guides 60cm




GUILAT2
Lateral guides 110cm




GUILAT1
Lateral guides 126cm

Accessoires



GUILAT3
Guides latéraux 60cm



GUILAT2
Guides latéraux 110cm



GUILAT1
Guides latéraux 126cm